


**Figure 2.2** ► *Materials Production Energy Needs, 1981 – 2005*

**Key point:** China accounts for the bulk of energy demand growth for manufacturing in the past twenty-five years.



Note: North America includes Canada, Mexico and US. Europe includes EU27 excluding three Baltic States, and including Albania, Bosnia, Croatia, Iceland, Former Yugoslav Republic of Macedonia, Norway, Serbia, Switzerland and Turkey.

Source: IEA data.