


Figure 2.3 ► *Industrial Direct CO₂ Emissions by Sector, 2004*

Key point: Three sectors: iron and steel, non-metallic minerals, and chemicals and petrochemicals account for 70% of industrial CO₂ emissions.



Note: Includes coke ovens, blast furnaces and process CO₂ emissions. Excludes emissions in power supply; assumes 75% carbon storage for all petrochemical feedstocks.

Source: IEA statistics.